

FIG. 3








FIG. 4


NOTE: LATCH









**FIG. 7**





**FIG. 9**





**FIG.10**





	0.0°	3.75°	7.5°	11.25°	15.0°	18.75°	22.5°	26.25°	30.0°	33.75°	37.5°	41.25°	45.0°	48.75°	52.5°	56.25°	60°
A	+	-	+	+	+	+	-	+	-	+	+	+	-	+	+	+	-
B	-	+	+	+	-	+	-	+	+	+	+	-	+	+	+	+	-
C	+	+	-	-	-	-	+	+	-	-	-	+	+	+	+	+	-

11.25° Between Magnets  
3.75° / Phase




FIG.12A




FIG.12B






FIG.12C




FIG. 12E

Delta Connection

Three Phase

Parallel Connection





FIG. 12D



M1, M2 = Module Number

FIG. 12G

Y Connection  
Three Phase  
Parallel Connection




FIG. 12F